

# Go Primer





**THINNING** 8 - 12%



COVERAGE 10 - 12m<sup>2</sup>/L



**APPLICATION** brush, roller or airless spray gun



**DRYING** ½ - 1 hour

## **Plasterboard** primer

### » Fills the surface perfectly, smoothing out all imperfections

White, water-based acrylic primer for interior use with a great filling ability, suitable for plasterboards. It offers very good adhesion, smoothing out especially the superficial uneven parts of the plasterboard. It effectively contributes to the final opacity, it can be repainted with any emulsion paint and it is almost odorless.

### A/h (WB) Binding Primers.

- VOC Limit Value: 30g/L.
- Maximum VOC concentration of the ready to use product: 29g/L.

### » Contributes to the final opacity

### » Can be repainted with any emulsion paint

TECHNICAL DATA	
Density ISO 2811 @ 25°C	1.65 g/mL (±0.03)
Solids Content w/w ISO 3251	67.5% (±3)
Viscosity ASTM D 562-05 @ 25°C	110KU (±15)
Application Viscosity ASTM D 562-05 @ 25°C	85 KU (±15)
Gloss Level @ 60° ISO 2813	<3 GU
Gloss Level @ 85° ISO 2813	<12 GU
pH	8.5 - 9.5
Whiteness Index ASTM E 313-98	84.5 (±1.5)
Yellowness Index ASTM E 313-98	1.5 (±0,5)
Coverage per coat	10 - 12 m²/L*
Recommended dry film thickness (1 coat)	40 μm (±5μm)

<sup>\*</sup> Depending on the application method and the surface absorption.











# PAINTS DRIVEN BY INNOVATION

# Go Primer

# Plasterboard primer

### SURFACE PREPARATION

To ensure good adhesion, the surface must be dry, solid, and free of dust, grease, residues, blistered paint, etc. Avoid dust generation and exposure to it.

- » On new surfaces: Before applying the topcoat, apply one coat of KRAFT GO PRIMER.
- » **On surfaces that need repair:** Use KRAFT SPACHTEL or KRAFT PUTTY or a suitable KRAFT repairing material.
- » At plasterboard joints: before GO PRIMER is applied KRAFT HAFT to insulate the putty.

### APPLICATION INSTRUCTIONS

- » Before start painting, thin the paint 8-12% v/v with tap water and stir well
- » You can apply with a brush, a roller or an airless spray gun.
- » Apply one coat of KRAFT GO PRIMER for an ideal result. Then apply two coats of the KRAFT topcoat.
- » Minimum recoating time: 3-4 hours.
- » Dry to touch: ½-1 hour at 25°C and 50% relative humidity. Drying time is subject to weather conditions.
- » Do not apply at temperatures below 5°C or above 35°C and at a relative humidity 65% or higher.

### AFTER USE INSTRUCTIONS

- » Clean the tools immediately with warm water and soap.
- » Close the canister well to preserve it in good condition for future use. Store before or after opening in a cool place, avoiding sunlight or frost conditions.

### **PACKAGING**

Available in White in 3L and 9L containers.

# HEALTH, SAFETY & ENVIRONMENTAL PROTECTION INSTRUCTIONS

Read the label carefully before use. For more information, please refer to the Safety Data Sheet.

Poison Centre Telephone:

+30 210 7793 777

### **STORAGE**

Store the product at temperatures between 5°C and 35°C away from direct sunlight and rain, for maximum 24 months from the date of production. Keep containers tightly closed when not in use.